

INCHES	DECIMAL	MM.	CM.
1/64 =	0.015625 =	0.396875 =	0.039687
1/32 =	0.031250 =	0.793750 =	0.079375
3/64 =	0.046875 =	1.190625 =	0.119062
1/16 =	0.062500 =	1.587500 =	0.158750
5/64 =	0.078125 =	1.984375 =	0.198437
3/32 =	0.093750 =	2.381250 =	0.238125
7/64 =	0.109375 =	2.778125 =	0.277812
1/ 8 =	0.125000 =	3.175000 =	0.317500
9/64 =	0.140625 =	3.571875 =	0.357187
5/32 =	0.156250 =	3.968750 =	0.396875
11/64 =	0.171875 =	4.365625 =	0.436562
3/16 =	0.187500 =	4.762500 =	0.476250
13/64 =	0.203125 =	5.159375 =	0.515937
7/32 =	0.218750 =	5.556250 =	0.555625
15/64 =	0.234375 =	5.953125 =	0.595312
- 1/ 4 =	0.250000 =	6.350000 =	0.635000
17/64 =	0.265625 =	6.746875 =	0.674687
9/32 =	0.281250 =	7.143750 =	0.714375
19/64 =	0.296875 =	7.540625 =	0.754062
- 5/16 =	0.312500 =	7.937500 =	0.793750
21/64 =	0.328125 =	8.334375 =	0.833437
11/32 =	0.343750 =	8.731250 =	0.873125
23/64 =	0.359375 =	9.128125 =	0.912812
- 3/ 8 =	0.375000 =	9.525000 =	0.952500
25/64 =	0.390625 =	9.921875 =	0.992187
13/32 =	0.406250 =	10.318750 =	1.031875
27/64 =	0.421875 =	10.715625 =	1.071562
- 7/16 =	0.437500 =	11.112500 =	1.111250
29/64 =	0.453125 =	11.509375 =	1.150937
15/32 =	0.468750 =	11.906250 =	1.190625
31/64 =	0.484375 =	12.303125 =	1.230312
- 1/ 2 =	0.500000 =	12.700000 =	1.270000
33/64 =	0.515625 =	13.096875 =	1.309687
17/32 =	0.531250 =	13.493750 =	1.349375
35/64 =	0.546875 =	13.890625 =	1.389062
- 9/16 =	0.562500 =	14.287500 =	1.428750
37/64 =	0.578125 =	14.684375 =	1.468437
19/32 =	0.593750 =	15.081250 =	1.508125
39/64 =	0.609375 =	15.478125 =	1.547812
- 5/ 8 =	0.625000 =	15.875000 =	1.587500
41/64 =	0.640625 =	16.271875 =	1.627187
21/32 =	0.656250 =	16.668750 =	1.666875
43/64 =	0.671875 =	17.065625 =	1.706562
11/16 =	0.687500 =	17.462500 =	1.746250
45/64 =	0.703125 =	17.859375 =	1.785937
23/32 =	0.718750 =	18.256250 =	1.825625
47/64 =	0.734375 =	18.653125 =	1.865312
3/ 4 =	0.750000 =	19.050000 =	1.905000
49/64 =	0.765625 =	19.446875 =	1.944687
25/32 =	0.781250 =	19.843750 =	1.984375
51/64 =	0.796875 =	20.240625 =	2.024062
13/16 =	0.812500 =	20.637500 =	2.063750
53/64 =	0.828125 =	21.034375 =	2.103437
27/32 =	0.843750 =	21.431250 =	2.143125
55/64 =	0.859375 =	21.828125 =	2.182812
7/ 8 =	0.875000 =	22.225000 =	2.222500
57/64 =	0.890625 =	22.621875 =	2.262187
29/32 =	0.906250 =	23.018750 =	2.301875
59/64 =	0.921875 =	23.415625 =	2.341562
15/16 =	0.937500 =	23.812500 =	2.381250
61/64 =	0.953125 =	24.209375 =	2.420937
31/32 =	0.968750 =	24.606250 =	2.460625
63/64 =	0.984375 =	25.003125 =	2.500312